

**527 Third Street
Improvements since June 2005**

Exterior

**Concrete parking pad (2 cars)
Sidewalk
Storage shed
Wood privacy fence on left
Re-lead glass surround (foyer)**

Interior

**Re-stained 1st floor woodwork
Painted foyer, den, and living room**

Kitchen

**Light fixtures
Dishwasher
Under cabinet lights
Sliding shelves in cabinets**

Second floor

**Hall chandeliers
Bathroom light
Plantation shutters (MBR)
Ceiling fan (MBR)**

Fireplaces

Wittikinds' inspection, servicing, & installation of ventless gas logs (LR)

Wittikinds' inspection & servicing of den fireplace

Wittikinds' inspection, servicing, & installation of wood stove (MBR)